

Preliminary List of Collapsed and Partially Damaged Monuments owing to Earthquake on 25th April 2015 (2072/1/12)

Sn	Name of Monuments	Location	PMZ / District	Condition Report
1	Maju Dega	Hanumandhoka	HDK Durbar PMZ	Collapsed
2	Trailokyamohana Temple	Hanumandhoka	HDK Durbar PMZ	Collapsed
3	Kamdev Temple	Hanumandhoka	HDK Durbar PMZ	Collapsed
4	Kastamandapa	Hanumandhoka	HDK Durbar PMZ	Collapsed
5	Vishnu Temple - the north of Magu Dega	Hanumandhoka	HDK Durbar PMZ	Collapsed
6	Shiva Temple-in the front of Telegu Temple	Hanumandhoka	HDK Durbar PMZ	Collapsed
7	Pratap stanga	Hanumandhoka	HDK Durbar PMZ	Collapsed
8	Radhakrishna Temple	Hanumandhoka	HDK Durbar PMZ	Collapsed
9	Kakeswor	Hanumandhoka	HDK Durbar PMZ	Collapsed
10	shiva parvati Temple	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
11	Vishnu Temple	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
12	Degu Taleju	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
13	Maha Vishnu Temple	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
14	Basantapur Palace-collapsed the upper portion of the four tower.	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
15	Nagara house	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
16	Gaddhi Baithak	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
17	Nasal chowk-crack the wall of west and south building	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
18	Crack all the part of Palace except the Mulchowk	Hanumandhoka	HDK Durbar PMZ	Partially Damaged
19	Charnarayan Temple	Patan Durbar Square	Patan Durbar PMZ	Collapsed
20	Shankarnarayan Temple	Patan Durbar Square	Patan Durbar PMZ	Collapsed

21	Manimandap	Patan Durbar Square	Patan Durbar PMZ	Collapsed
22	Pillar of Yognarendra Malla	Patan Durbar Square	Patan Durbar PMZ	Collapsed
23	Radha Krishna Temple in the north of the Darbar square	Patan Durbar Square	Patan Durbar PMZ	Collapsed
24	Bishweswor Mahadev Temple	Patan Durbar Square	Patan Durbar PMZ	Partially Damaged
25	Teleju of mulchowke	Patan Durbar Square	Patan Durbar PMZ	Partially Damaged
26	Agamchhe of Mulchowk	Patan Durbar Square	Patan Durbar PMZ	Partially Damaged
27	Sundari chowke	Patan Durbar Square	Patan Durbar PMZ	Partially Damaged
28	Radha krishna in the north of Darbar squire	Patan Durbar Square	Patan Durbar PMZ	Partially Damaged
29	Bahadur Shah Palace	Patan Durbar Square	Patan Durbar PMZ	Partially Damaged
30	Vatsala devi Temple	Bhaktapur	Bkt Durbar PMZ	Collapsed
31	Silu Mahadev Temple	Bhaktapur	Bkt Durbar PMZ	Collapsed
32	Kedarnath Temple	Bhaktapur	Bkt Durbar PMZ	Collapsed
33	Betalpati	Bhaktapur	Bkt Durbar PMZ	Collapsed
34	Chyasingmandap of bhelukhel	Bhaktapur	Bkt Durbar PMZ	Collapsed
35	Western Entrance of darbar Squire	Bhaktapur	Bkt Durbar PMZ	Collapsed
36	Tentative 25-30 traditional houses which were belong to PMZ	Bhaktapur	Bkt Durbar PMZ	Collapsed
37	Harisankar Sattal	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
38	Lal Baithak	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
39	Nyatapole Temple	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
40	Bhairavnath Temple	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
41	Yesamari Sattal	Bhaktapur	Bkt Durbar PMZ	Partially Damaged

42	Pujari Matha	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
43	Metal Museum	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
44	Art gallery	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
45	Police house	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
46	Siddhilaxmi	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
47	Narayan Temple	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
48	Nriteswor	Bhaktapur	Bkt Durbar PMZ	Partially Damaged
49	Jayabageswori Temple	Chabahil	Pashupati PMZ	Partially Damaged
50	Mahamirtunejay Temple	Chabahil	Pashupati PMZ	Partially Damaged
51	Narsimha Temple	Chabahil	Pashupati PMZ	Partially Damaged
52	Agni Matha	Chabahil	Pashupati PMZ	Partially Damaged
53	Tamreswor Mahadev Temple	Chabahil	Pashupati PMZ	Partially Damaged
54	Guheswori Temple	Guhyeshwori	Pashupati PMZ	Partially Damaged
55	Sattal - west to Guheswori Temple	Guhyeshwori	Pashupati PMZ	Partially Damaged
56	Sattal - east to Guheswori Temple	Guhyeshwori	Pashupati PMZ	Partially Damaged
57	Sattal of north to Guheswori Temple	Guhyeshwori	Pashupati PMZ	Partially Damaged
	Five shiva Temple inside White sattal of			
58	Guheswori	Guhyeshwori	Pashupati PMZ	Partially Damaged
59	Vishwarupa Temple	Mrigasthali	Pashupati PMZ	Collapsed
60	Radhakrishna Temple	Mrigasthali	Pashupati PMZ	Collapsed
	Eight Shiva Temple of Mirgasthali-			
	Among them two are completely			
61	collapsed	Mrigasthali	Pashupati PMZ	Partially Damaged
62	Ram Sita and Laxman Temple	Mrigasthali	Pashupati PMZ	Partially Damaged
	Nine Shiva Temple in the front of the			
63	Viavarupa Temple	Mrigasthali	Pashupati PMZ	Partially Damaged
64	Gorekhnath Temple	Mrigasthali	Pashupati PMZ	Partially Damaged
	Shivaparvati Temple in the front of			
65	gorekhnath Temple	Mrigasthali	Pashupati PMZ	Partially Damaged
	Bhandarghar, gorekhnath Temple			
66	complex	Mrigasthali	Pashupati PMZ	Partially Damaged

67	Ashram of yoginaraharinath	Mrigasthali	Pashupati PMZ	Partially Damaged
68	Chandreswor Sattal	Mrigasthali	Pashupati PMZ	Partially Damaged
69	Seto Shiva Temple, East of Bagmati river	Ram Temple Area	Pashupati PMZ	Partially Damaged
70	Shiva Temple	Ram Temple Area	Pashupati PMZ	Partially Damaged
71	Ram Temple,Bank of Bagmati river	Ram Temple Area	Pashupati PMZ	Partially Damaged
72	Ram kuti,Bank of Bagmati river	Ram Temple Area	Pashupati PMZ	Partially Damaged
73	Laxmannarayan Temple	Ram Temple Area	Pashupati PMZ	Partially Damaged
74	Ram Temple, Bank of Bagmati river	Ram Temple Area	Pashupati PMZ	Partially Damaged
75	Two Shiva Temple close to nanak sattal	West of Bagmati	Pashupati PMZ	Collapsed
76	Three Shiva Temple of Basmeswor chowke	West of Bagmati	Pashupati PMZ	Partially Damaged
77	Nanak Satta	West of Bagmati	Pashupati PMZ	Partially Damaged
78	House in the backside of the shiva Temple	West of Bagmati	Pashupati PMZ	Partially Damaged
79	Panchha Deval	West of Bagmati	Pashupati PMZ	Partially Damaged
80	Birdhasarma arround Panchadeval	West of Bagmati	Pashupati PMZ	Partially Damaged
81	Bajraghar	West of Bagmati	Pashupati PMZ	Partially Damaged
82	Sankarachharya Matha	West of Bagmati	Pashupati PMZ	Partially Damaged
83	Kulananda Jha sattal	West of Bagmati	Pashupati PMZ	Partially Damaged
84	Gyhmpe pati	West of Bagmati	Pashupati PMZ	Partially Damaged
85	Agamghar	West of Bagmati	Pashupati PMZ	Partially Damaged
86	Saptami Sattal	West of Bagmati	Pashupati PMZ	Partially Damaged
87	Bhasar Tahabil Office	West of Bagmati	Pashupati PMZ	Partially Damaged
88	Rudragadeswor Sattal	West of Bagmati	Pashupati PMZ	Partially Damaged
89	Sano Sadabarta	West of Bagmati	Pashupati PMZ	Partially Damaged
90	Sankarnarayan Sattal	West of Bagmati	Pashupati PMZ	Partially Damaged
91	Mahasnan Ghar	West of Bagmati	Pashupati PMZ	Partially Damaged
92	Gurujeu Sattal	West of Bagmati	Pashupati PMZ	Partially Damaged
93	Shiva Temple in the north of Pasupati complex	West of Bagmati	Pashupati PMZ	Partially Damaged

	Three Shiva Temple in the front of			
94	Basuki Temple	West of Bagmati	Pashupati PMZ	Partially Damaged
95	Basuki Temple	West of Bagmati	Pashupati PMZ	Partially Damaged
96	Lal Ganesh Temple	West of Bagmati	Pashupati PMZ	Partially Damaged
97	Surya Temple,close to lal Ganesh	West of Bagmati	Pashupati PMZ	Partially Damaged
98	Pasupati Paksala	West of Bagmati	Pashupati PMZ	Partially Damaged
99	Pati of Sitala Devi	West of Bagmati	Pashupati PMZ	Partially Damaged
100	Sriko Paksala	West of Bagmati	Pashupati PMZ	Partially Damaged
101	Jitjungaparkaseswor Sattal and Temple	West of Bagmati	Pashupati PMZ	Partially Damaged
102	Nava Durga Sattal	West of Bagmati	Pashupati PMZ	Partially Damaged
103	Rajrajeswori Sangeet Asram	West of Bagmati	Pashupati PMZ	Partially Damaged
104	Parkaseswor Temple	West of Bagmati	Pashupati PMZ	Partially Damaged
105	Sattal of Kirateswor Temple	West of Bagmati	Pashupati PMZ	Partially Damaged
106	Kirateswor Sangeet Ashram	West of Bagmati	Pashupati PMZ	Partially Damaged
107	Kirateswor yangasala	West of Bagmati	Pashupati PMZ	Partially Damaged
108	Four Shiva Temple of Gaurighat	West of Bagmati	Pashupati PMZ	Partially Damaged
109	Shiva Temple of Guheswori	West of Bagmati	Pashupati PMZ	Partially Damaged
110	Anatanarayan,Batsalla area	West of Bagmati	Pashupati PMZ	Partially Damaged
111	Pancha Ganesh, Batsalla area	West of Bagmati	Pashupati PMZ	Partially Damaged
112	Annatapur Temple	Swayambhu Hill	Swayambhu PMZ	Collapsed
	Tibetan chorten-in the south of main			
113	stupa	Swayambhu Hill	Swayambhu PMZ	Collapsed
	Two houses in the south-east of			
114	Shantipur	Swayambhu Hill	Swayambhu PMZ	Collapsed
	Two traditional house in the north of			
115	main stupa	Swayambhu Hill	Swayambhu PMZ	Collapsed
116	Karmaraj Mahavihara	Swayambhu Hill	Swayambhu PMZ	Collapsed
117	Deva Dharma Mahavihara	Swayambhu Hill	Swayambhu PMZ	Collapsed
118	Shantipur	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
119	Basubhandhu Chaitya	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
120	Pati in the east of shantipur	Swayambhu Hill	Swayambhu PMZ	Partially Damaged

121	One traditional house in the south of shantipur	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
122	Pratappur	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
123	Gyanmala bhajan sattal	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
124	Museum	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
125	One traditional house in the south of Chhaita park	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
126	Two traditional houses in the north of Hariti Temple	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
127	Three traditional houses in the south of shantipur	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
128	Pillar in the west of main stupa	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
129	Karmaraj Mahavihar	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
130	Devadharma Mahavihar	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
131	Sattal around Manjusri Temple	Swayambhu Hill	Swayambhu PMZ	Partially Damaged
132	Crack on the trayodasabhuvana and tilted the pinnacle of the stupa	Bouddha	Bouddha PMZ	Partially Damaged
133	Two small stupa in the east and north corner of the stupa	Bouddha	Bouddha PMZ	Partially Damaged
134	Sattal of south direction	Changu Narayan	Changu Narayan PMZ	Collapsed
135	Sattal of south west direction	Changu Narayan	Changu Narayan PMZ	Collapsed
136	Sattal of north-east direction	Changu Narayan	Changu Narayan PMZ	Collapsed
137	Sattal of east-south direction	Changu Narayan	Changu Narayan PMZ	Collapsed
138	Shiva Temple	Changu Narayan	Changu Narayan PMZ	Collapsed
139	More than ten traditional residential house belong to protected area	Changu Narayan	Changu Narayan PMZ	Collapsed

140	Changunarayan Temple	Changu Narayan	Changu Narayan PMZ	Partially Damaged
141	Kileswor Temple	Changu Narayan	Changu Narayan PMZ	Partially Damaged
142	Bhimsen Stambha - DHARAHARA	Sundhara	Kathmandu	Collapsed
143	Jaisi Deval	Jaishi Dewal	Kathmandu	Collapsed
144	Hemhiranya Narayan Temple	Tirpureswor	Kathmandu	Collapsed
145	Tirpureswor Mahadev Temple	Tirpureswor	Kathmandu	Partially Damaged
146	Bombiketeswor Temple	Pachali	Kathmandu	Partially Damaged
147	Jaganath Temple	Pachali	Kathmandu	Partially Damaged
148	Krishna Temple	Pachali	Kathmandu	Partially Damaged
149	Shiva Temple	Pachali	Kathmandu	Partially Damaged
150	Sattal of Shiva Temple	Pachali	Kathmandu	Partially Damaged
151	Shova Bhagavati	Shobha Bhagawati	Kathmandu	Partially Damaged
152	Gorakhnath Temple	Thapathali	Kathmandu	Partially Damaged
153	Shiva Temple	Ranipokheri	Kathmandu	Partially Damaged
154	Darbar High school	Ranipokheri	Kathmandu	Partially Damaged
155	Ranamukteswor Temple and sattal	Ranamukteswor	Kathmandu	Partially Damaged
156	Indrayani	Shobhabagwati	Kathmandu	Partially Damaged
157	Mahalaxmi Temple	Balambu	Kathmandu	Partially Damaged
158	Mahalaxmi Temple	Thankot	Kathmandu	Partially Damaged
159	Bishnu Devi Temple	Satungal	Kathmandu	Partially Damaged
160	Adinath	Kirtipur	Kathmandu	Partially Damaged
161	Jalabinayak Temple and Sattal	Kirtipur	Kathmandu	Partially Damaged
162	Shivaparvati Temple kirtipur	Kirtipur	Kathmandu	Partially Damaged
163	Loha Deval, Kirtipur	Kirtipur	Kathmandu	Partially Damaged
164	Chilancho chhaitya	Kirtipur	Kathmandu	Partially Damaged
	Shhikara Temple ,East side of			
165	Chilanchho	Kirtipur	Kathmandu	Partially Damaged
166	Pati, Gutpau tol	Kirtipur	Kathmandu	Partially Damaged
167	Sorhakhutte Pati	Kirtipur	Kathmandu	Collapsed

168	Bagh Bhairav Temple	Kirtipur	Kathmandu	Partially damaged
169	Shiva Parvati Temple	Kirtipur	Kathmandu	Partially Damaged
170	Narayan Temple	Kirtipur	Kathmandu	Partially Damaged/tilted
171	Lohan Dega, Gupta Pau	Kirtipur	Kathmandu	Partially damaged
	Sorhakhutte Pati	Kirtipur	Kathmandu	Collapsed
	Bagh Bhairav Temple	Kirtipur	Kathmandu	Partially damaged
	Shiva Parvati Temple	Kirtipur	Kathmandu	Partially Damaged
	Narayan Temple	Kirtipur	Kathmandu	Partially Damaged/tilted
	Lohan Dega, Gupta Pau	Kirtipur	Kathmandu	Partially damaged
172	Vajrayogini Temple	Sankhu	Kathmandu	Partially Damaged
	Padmagiri Dharma Dhatu Chaitya			
173	Mahavihara , Vajrayogi complex	Sankhu	Kathmandu	Partially Damaged
174	Jyotiligeswor Temple	Sankhu	Kathmandu	Partially Damaged
175	Madhab Narayan Dhochhe	Sankhu	Kathmandu	Partially Damaged
176	Viseswornath Temple	Sankhu	Kathmandu	Partially Damaged
177	Simha Sattal, Vajrayogi complex	Sankhu	Kathmandu	Partially Damaged
178	Khadga Yogini Temple	Sankhu	Kathmandu	Partially Damaged
179	Bishweshwor Mahadev Temple	Sankhu	Kathmandu	Partially Damaged
180	Jyotilingeshwor Mahadeva	Sankhu	Kathmandu	Partially Damaged
181	Madhav Narayan Dhyo Chhen	Sankhu	Kathmandu	Partially Damaged
182	Kumari Mandap	Sankhu	Kathmandu	Partially Damaged
183	Padma Pani Lokeshwor	Sankhu	Kathmandu	Partially Damaged
184	Dharavan Mahadev	Pushal	Kathmandu	Collapsed
185	Pati - Ganesh Temple Complex	Dharmasthali	Kathmandu	Collapsed
186	Mahankal Temple	Dharmasthali	Kathmandu	Collapsed
187	Two Dewals	Dharmasthali	Kathmandu	Collapsed
188	Agam Chhen	Dharmasthali	Kathmandu	Collapsed
189	Lachhighar - Pati	Dharmasthali	Kathmandu	Partially Damaged
190	Bramha, Vishnu, Hanuman	Dharmasthali	Kathmandu	Partially Damaged
191	Bhimsen temple	Dharmasthali	Kathmandu	Partially Damaged
192	Ganesh Temple	Dharmasthali	Kathmandu	Partially Damaged

193	Narayan Temple	Dharmasthali	Kathmandu	Partially Damaged
194	Siddheshwor Temple	Jitpurfedi	Kathmandu	Partially Damaged
195	Two Pati - Panch Mane Bhanjyang	Jitpurfedi	Kathmandu	Partially Damaged
196	Tarakeshwor Temple - including 2 Kuti	Jitpurfedi	Kathmandu	Collapsed
197				
198				
199	Jagatnarayan Temple	Sankhamul	Lalitpur	Collapsed
197	Shiva Temple	Sundhara	Lalitpur	Collapsed
198	Jagatnarayan Matha	Sankhamul	Lalitpur	Partially Damaged
199	Khumbheswor	Bagalamukhi	Lalitpur	Partially Damaged
193	Vishnu Temple	Ikhalkhu	Lalitpur	Partially Damaged
191	Stupa of	Pulchowk	Lalitpur	Partially Damaged
192	Bagalamukhi		Lalitpur	Partially Damaged
	Mahavihar related to Mishra in the east			
193	of nortn east of Ashokan chaitya	Pulchowk	Lalitpur	Partially Damaged
194	Sattal of Laijol	Thecho	Lalitpur	Collapsed
195	Sattal of Pukhushi	Thecho	Lalitpur	Collapsed
196	Sattal of Lachhijo	Thecho	Lalitpur	Collapsed
197	Pati of Misaphalachha	Thecho	Lalitpur	Collapsed
198	Balkumari Temple	Thecho	Lalitpur	Partially Damaged
199	Sattal of Chapal	Thecho	Lalitpur	Partially Damaged
200	Balkumai pitha	Thecho	Lalitpur	Partially Damaged
201	Brahmayani Temple	Thecho	Lalitpur	Partially Damaged
202	Birngareswor Pati	Sunakothi	Lalitpur	Collapsed
203	Birngareswor Mahadev Temple	Sunakothi	Lalitpur	Partially Damaged
204	Uma Maheswor Pati	Sunakothi	Lalitpur	Partially Damaged
205	Brihaspati Temple	Harisiddhi	Lalitpur	Partially Damaged
206	Ram Temple	Harisiddhi	Lalitpur	Partially Damaged
207	Bhawani Temple	Harisiddhi	Lalitpur	Partially Damaged
208	Narayan Temple of thhaibahani tole	Godawari	Lalitpur	Partially Damaged
209	Phulchoki Temple of thhaibahani tole	Godawari	Lalitpur	Partially Damaged

210	Ganesh Temple of Ganeshsthan	Godawari	Lalitpur	Partially Damaged
211	Guthighar of Lakhetole	Godawari	Lalitpur	Partially Damaged
212	Temple of Ram Temple and sattal	Godawari	Lalitpur	Partially Damaged
213	Naudhara Temple	Godawari	Lalitpur	Partially Damaged
214	Swete Baraha Temple	Godawari	Lalitpur	Partially Damaged
215	Pond of Godabari	Godawari	Lalitpur	Partially Damaged
216	Bishankhu Narayan Temple	Godawari	Lalitpur	Partially Damaged
217	VajraVarahi Temple / Tilted	Chapagaon	Lalitpur	Partially Damaged
218	Rato Machhindranath Temple	Bungamati	Lalitpur	Collapsed
219	Bhairab Temple	Bungamati	Lalitpur	Collapsed
220	Pancha Buddha Temple	Bungamati	Lalitpur	Collapsed
221	Manokamana Mai Temple	Bungamati	Lalitpur	Collapsed
222	Guthitar	Bungamati	Lalitpur	Collapsed
223	Prathamur Mahavihar	Bungamati	Lalitpur	Partially Damaged
224	Karyavinayak	Bungamati	Lalitpur	Partially Damaged
225	Rudrayani temple	Khokana	Lalitpur	Partially Damaged
226	Duchhe	Khokana	Lalitpur	Partially Damaged
227	Ganachkra Ghar	Khokana	Lalitpur	Partially Damaged
228	Balakhu Ganesh Pati	Bhaktapur	Bhaktpur	Collapsed
229	Sattal - Narayan Temple	Chupighat	Bhaktpur	Collapsed
230	Vishnubir	Thimi	Bhaktpur	Collapsed
231	Dakchinvarahi temple	Thimi	Bhaktpur	Partially Damaged
232	Wamune Pati	Thimi	Bhaktpur	Partially Damaged
233	Mahalaxmi	Bode	Bhaktpur	Partially Damaged
234	Tulanarayan temple,Indreswor complex	Panauti	Kavrepalanchowk	Partially Damaged
235	Pasupati temple,Layaku	Panauti	Kavrepalanchowk	Partially Damaged
236	Dhaneswor sattal	Panauti	Kavrepalanchowk	Partially Damaged
237	Shiva Temple - Chandeswori Complex	Banepa	Kavrepalanchowk	Collapsed
238	Shiva Temple - Banepa Dabali	Banepa	Kavrepalanchowk	Partially Damaged
239	Main sanctum of namobuddha	Namo Buddha	Kavrepalanchowk	Partially Damaged
240	Bhimsen temple	Dapcha	Kavrepalanchowk	Partially Damaged

241	Bhimsen temple	Kathikanda	Kavrepalanchowk	Partially Damaged
242	Brahmayani	Deupur	Kavrepalanchowk	Partially Damaged
243	Tripurasundari temple	Dolakha	Dolakha	Partially Damaged
244	Narayan temple of Kotchhe	Dolakha	Dolakha	Partially Damaged
245	Narayan Temple of Dungal	Dolakha	Dolakha	Partially Damaged
246	Taleju temple	Dolakha	Dolakha	Partially Damaged
247	Bhimsen temple	Lyanglyang	Ramechhap	Partially Damaged
248	Lamjung Durbar	Lamjung	Lamjung	Partially Damaged
249	Tallokot kalika temple	Gorkha Durbar	Gorkha	Collapsed
250	Pandit Pati	Gorkha Durbar	Gorkha	Collapsed
251	Gorakhnath temple	Gorkha Durbar	Gorkha	Collapsed
252	Guheswori	Gorkha Durbar	Gorkha	Collapsed
253	Sri Vidhya temple	Gorkha Durbar	Gorkha	Collapsed
254	Damai Pati	Gorkha Durbar	Gorkha	Collapsed
255	Upallo kot temple	Gorkha Durbar	Gorkha	Collapsed
256	Tallo darbar	Gorkha Durbar	Gorkha	Partially Damaged
257	Sitalpati	Gorkha Durbar	Gorkha	Partially Damaged
258	Rangmahal	Gorkha Durbar	Gorkha	Partially Damaged
259	Upallo Darbar	Gorkha Durbar	Gorkha	Partially Damaged
260	Rot Pati	Gorkha Durbar	Gorkha	Partially Damaged
261	Pasupati	Gorkha Durbar	Gorkha	Partially Damaged
262	Chautaro of Ramshah	Gorkha Durbar	Gorkha	Partially Damaged
263	GaneshSthan	Gorkha Durbar	Gorkha	Partially Damaged
264	Manakamana	Manakamana	Gorkha	Collapsed
265	Taleju temple	Nuwakot Durbar	Nuwakot	Collapsed
266	Garadghar	Nuwakot Durbar	Nuwakot	Collapsed
267	Seven storied palace	Nuwakot Durbar	Nuwakot	Partially Damaged
268	Rangmahal	Nuwakot Durbar	Nuwakot	Partially Damaged
269	Bhairavi temple	Nuwakot Durbar	Nuwakot	Partially Damaged
270	Narayan temple	Nuwakot Durbar	Nuwakot	Partially Damaged
271	Vishnu temple	Nuwakot Durbar	Nuwakot	Partially Damaged

272	Lampati	Nuwakot Durbar	Nuwakot	Partially Damaged
273	Seto Pati	Nuwakot Durbar	Nuwakot	Collapsed
274	Dhami Ghar	Nuwakot Durbar	Nuwakot	Partially Damaged
275	Bhajan Pati	Nuwakot Durbar	Nuwakot	Partially Damaged
276	Ghanta Ghar	Nuwakot Durbar	Nuwakot	Collapsed
277	Chaitya - North to Bhairavi Temple	Nuwakot Durbar	Nuwakot	Collapsed
278	Chaitya - South to Bhairavi Temple	Nuwakot Durbar	Nuwakot	Partially Damaged
279	Pujari Ghar - South to durbar gate	Nuwakot Durbar	Nuwakot	Partially Damaged
280	Dware Ghar	Nuwakot Durbar	Nuwakot	Partially Damaged
281	Bhagawati Temple	Nuwakot Durbar	Nuwakot	Partially Damaged
282	Ticket Counter	Nuwakot Durbar	Nuwakot	Partial Damage/ Cracks
283	Security Compound Wall	Nuwakot Durbar	Nuwakot	Partially Damaged

